

## Replacement Sheet 1/11








Fig. 1









#### Replacement Sheet 5/11

### Switching Sequence of A, A', B, B', C, C' for Figure 2A

- 1 Close A, A', C, C' (reset Cs1, Cs2)
- 2 Float all switches
- 3 Close B, B' (charge Cs1, Cs2)
- 4 Float all switches
- 5 Close A, A' (clamp strip to ground)
- 6 Measure 1, 2
- 7 goto step 1 (if desired)

### Fig. 3A

#### Switching Sequence of A, A', B, B', C, C' for Figure 2B

- 1 Reset Counters CT1, CT2
- 2 Close A, A', C, C' (reset Cs1, Cs2)
- 3 Float all switches
- 4 Close B, B' (charge Cs1, Cs2)
- 5 Float all switches
- 6 Close A, A' (clamp strip to ground)
- 7 If (VCs1 < Vt) then increment CT1;
  - If (VCs2 < Vt) then increment CT2
- 8 If ((VCs1 <Vt) or (VCs2 <Vt)) then goto step 3
- 9 Float all switches
- 10 goto step 1 to repeat (if desired)

Fig. 3B





Fig. 4






Fig. 8a






Fig. 8b

# Replacement Sheet 9/11





# Replacement Sheet 10/11




Fig. 11




Fig. 12

### Replacement Sheet 11/11




Fig. 13




Fig. 14